

Little Tonsina Construction Update Report

Report Date: 10/3/22

Work Time Frame: 10/3 - 10/10

Recent Work:

- Tutka placed the rest of the riprap up in front of both abutments last week.
- We reached 5000+ psi on our test cylinder breaks and only need 4000, so that's always promising. (nothing weird going on with the concrete) and the abutments were looking clean.

Upcoming Work:

- Girder placement

Photos:

Attached in email and to the pdf.







